

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401653255
Date Received:
05/25/2018

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10669
Name of Operator: NICKEL ROAD OPERATING LLC
Address: 1600 17TH STREET SUITE 2800
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name: _____
Phone: () Fax: ()
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
JENNIFER LIND	303-406-1117	JENNIFER.LIND@NICKELROADOPERATING.COM
DAN BRUGEMAN	303-253-4844	DAN.BRUGEMAN@NICKELROADOPERATING.COM

COGCC INSPECTION SUMMARY:

FIR Document Number: 682403558
Inspection Date: 05/14/2018 FIR Submit Date: 05/15/2018 FIR Status: _____

Inspected Operator Information:

Company Name: NICKEL ROAD OPERATING LLC Company Number: 10669
Address: 1600 17TH STREET SUITE 2800
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 454131

Location Name: Noble Number: 3N68W5 County: _____
Qtrqr: NWS Sec: 5 Twp: 3N Range: 68W Meridian: 6
W
Latitude: 40.254008 Longitude: -105.033646

FACILITY - API Number: 05-123- -00 Facility ID: 454131

Facility Name: Noble Number: 3N68W5
Qtrqr: NWS Sec: 5 Twp: 3N Range: 68W Meridian: 6
W
Latitude: 40.254008 Longitude: -105.033646

CORRECTIVE ACTIONS:

1 ☒ CA# 116346

Corrective Action: Install or repair required BMPs per Rule 1002.f. immediately. Date: 05/14/2018

Response: CA COMPLETED Date of Completion: 05/15/2018

Operator Comment: VEHICLE TRACKING CONTROL ADDED TO ACCESS POINT ON 5/15/18. ADJUSTMENTS HAVE ALSO BEEN MADE TO DITCHES AND SEDIMENT TRAPS IN ACCORDANCE WITH CDPHE FIELD-WIDE STORMWATER PERMIT, SITE-SPECIFIC PLAN AND REGULATIONS AS OF THE WEEK OF 5/15/18. TOP SOIL HAS BEEN PROPERLY SEGREGATED AND SEEDING OPERATIONS HAVE BEEN COMPLETED AS OF THIS WEEK.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

Note: Operator has not provided any further evidence demonstrating that topsoil was properly segregated per Rule 1002.b.(1). Based off field observations on 5/14/18, Operator did not salvage all the topsoil from the location.

OPERATOR COMMENT AND SUBMITTAL

Comment: CAs listed on this Inspection Report have been satisfied. Please see Corrective Actions & Responses tab for details.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: JENNIFER LIND

Signed: _____

Title: REGULATORY ANALYST

Date: 5/25/2018 10:11:19 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number Description

401653255	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files