

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/30/2018

Submitted Date:

06/05/2018

Document Number:

680303324**FIELD INSPECTION FORM**Loc ID 388627 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 50778Name of Operator: LEWIS & CLARK EXPLORATION COMPANYAddress: 8191 SOUTHPARK LN # 210City: LITTLETON State: CO Zip: 80120**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Andrews, Dave		david.andrews@state.co.us	
Ash, Margaret		margaret.ash@state.co.us	
Quint, Craig		craig.quint@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219633	WELL	PA	10/15/2003	OW	075-06607	DUBOIS 1	EI

**General Comment:**

Field Inspection performed in response to landowner complaint (verbal) received by Margaret Ash on 05/29/2018 @ approx. 4:15 pm. and relayed to N.E. Field Office. Field Inspector Schure contacted the landowner by telephone (Don Dickinson 970-580-8256) on 5/29/2018 @ approx. 4:21 pm for scheduling of on-site FIR @ 8:00 am on 05/30/2018.

Area of concern is located directly east of PA - Dubois #1 - 05-075-06607, approx. (1200') and directly south of Logan County Road 48 and adjacent to (west side) of North Sterling Reservoir Outlet ditch in Sec. 7 - 9N - 52W.

Area of concern is partially fenced (fence in disrepair) showing O-Sand crude on surface of adjacent soils and within fenced area in greater concentrations w/surface water (recent heavy rains in area). No identified PW pit at this location, suspected O&G historic dump site, (info. offered by landowner recollections). Landowner accompanied field inspection.

GPS Coordinates: 40.77423 / -103.21434

Approximate dimensions: (400') x (125')

Possible related Doc#200040677.

Note to COGCC: Consider creating a Facility ID # for this ODO issue.

**Location****Lease Road:**

Type	Other		
comment:	N/A		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	N/A		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	N/A		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
Crude Oil				
Comment:	Landowner complaint response. Forward to COGCC ODO PROGRAM			
Corrective Action:	Forward to COGCC ODO PROGRAM			Date: 05/30/2018

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Livestock		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 219633 Type: WELL API Number: 075-06607 Status: PA Insp. Status: EI

**Complaint**

Comment: Field Inspection performed in response to land-owner complaint (verbal) received by COGCC Field Inspection Unit and relayed to N.E. Field Office by Margaret Ash. Forwarding to COGCC ODO PROGRAM.

Corrective Action:

Date:

**COGCC Comments**

Comment

User

Date

FIR submitted for landowner complaint response. Forward to COGCC ODO Program.

schureky

06/05/2018

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680303334	Oil surfacing outside of fenced area	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4484918">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4484918</a>
680303335	Oil surfacing outside of fenced area	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4484919">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4484919</a>
680303336	Area of concern viewed from south to north / west edge	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4484920">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4484920</a>
680303337	Area of concern viewed west to east @ fence-line.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4484921">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4484921</a>
680303338	Area of concern fence-line viewed south to north	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4484922">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4484922</a>
680303339	Area of concern viewd north to south @ fence-line.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4484923">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4484923</a>
680303340	Area of concern north of fenced area	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4484924">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4484924</a>