

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/04/2018

Submitted Date:

06/05/2018

Document Number:

687902155**FIELD INSPECTION FORM**Loc ID 308183 Inspector Name: DURAN, JOHN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10084Name of Operator: PIONEER NATURAL RESOURCES USA INCAddress: 5205 N O'CONNOR BLVD STE 200City: IRVING State: TX Zip: 75039**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263850	WELL	PR	09/17/2005	GW	071-07640	BEAN 33-26	PR

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?**Fencing/:**

Type	PIT		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Vertical Separator	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	There are 2 Unmarked deadman, 2 Marked deadman		
Corrective Action:	Mark all deadman.		Date: 07/05/2018

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities				
Facility ID: 263850	Type: WELL	API Number: 071-07640	Status: PR	Insp. Status: PR
Producing Well				
Comment:	PR			
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: YES

Pit ID: _____

Lat: _____

Long: _____

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:Liner Type: PlasticLiner Condition: Inadequate

Comment:

There are holes in liner.

Corrective Action

Fix and repair liner or replace liner.Date: 07/05/2018c**Fencing:**Fencing Type: LivestockFencing Condition: Adequate

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____

Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____

Oil Accumulation: NO2+ feet Freeboard: YES

Comment:

30' x 70'

Corrective Action

Date: _____

Monitoring:

Monitoring Type

Comment`

Chain

Yellow

COGCC Comments

Comment

User

Date

SEE : Equipment : deadman, SEE : Pits : liner

duranj

06/05/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687902156	Lease sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4485772
687902157	Well pad	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4485773
687902158	Deadman marker down	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4485775
687902159	Holes in liner	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4485776

687902160	Holes in liner	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4485777
687902161	Deadman marker down	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4485778