

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401665700  
Date Received:  
06/06/2018

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 SEVENTEENTH STREET #1400

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Lorne C Prescott</u>	<u>970 812 5311</u>	<u>lprescott@laramie-energy.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 674104417

Inspection Date: 05/14/2018

FIR Submit Date: 05/22/2018

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: LARAMIE ENERGY LLC

Company Number: 10433

Address: 1401 SEVENTEENTH STREET #1400

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 311747

Location Name: BCU Number: 13A Pad County: \_\_\_\_\_

Qtrqr: NENE Sec: 13 Twp: 9S Range: 93W Meridian: 6

Latitude: 39.281130 Longitude: -107.715760

FACILITY - API Number: 05-077-00 Facility ID: 311747

Facility Name: BCU Number: 13A Pad

Qtrqr: NENE Sec: 13 Twp: 9S Range: 93W Meridian: 6

Latitude: 39.281130 Longitude: -107.715760

CORRECTIVE ACTIONS:

1 CA# 116463

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 05/31/2018

Response: CA COMPLETED

Date of Completion: 05/29/2018

Operator Comment: BMPs on upslope side have been augmented. BMPs pictured in COGCC inspection photo #5 (Silt Fence) is deemed by professionals to be sufficient to accomodate regulatory requirments for down gradient sediment controls.

COGCC Decision: **Not Approved**

Not apparent if BMPs have been installed or if iOperator is being argumentative and should have submitted

COGCC Factual Review Request.  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: BMPs on upslope side have been augmented. BMPs pictured in COGCC inspection photo #5 (Silt Fence) is deemed by professionals to be sufficient to accomodate regulatory requirments for down gradient sediment controls.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lorne C Prescott

Signed: \_\_\_\_\_

Title: Reg & Enviro Compliance

Date: 6/6/2018 4:27:25 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

401665700	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files