

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/11/2018

Submitted Date:

07/11/2018

Document Number:

689301501

FIELD INSPECTION FORM

Loc ID 334611 Inspector Name: Holtz, Darin On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 7 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Elsener,		COGCC.inspections@caerus oilandgas.com	all Piceance inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278232	WELL	PR	09/24/2005	GW	045-10863	FEDERAL 16-6 (RD16)	SI

General Comment:

[Routine Field Inspection](#)

Location

Lease Road:			
Type	Access		
comment:			
Corrective ActionL			Date:

Overall Good:

Emergency Contact Number:	
Comment:	1-800-791-7691
Corrective Action:	
	Date:

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds on location		
Corrective Action:	Comply with Rule 603.f .		Date: 07/21/2018

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 3		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:	1 Meter run out of service		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Inadequate
Comment:	Inadequate berms around tank(s) see photo Holes in liner, and metal side leaning			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4)			Date: 08/11/2018

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 278232 Type: WELL API Number: 045-10863 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Well shut in at time of inspection, crew on site working on electrical for automation.

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): NO

Comment:

Pilot: Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Gravel				
		Compaction				
Ditches						
Seeding						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401700187	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4520537
689301502	Inspection Photo 689301502	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4520534