

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401711918

Date Received:

07/24/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Beebe, Sabre		SanJuanCOGCC@bp.com Sabre.Beebe@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680601755
Inspection Date: 07/10/2017 FIR Submit Date: 07/12/2017 FIR Status:

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 325646

Location Name: CRAIG GAS UNIT-N33N10W Number: 24SENW County: LA PLATA
Qtrqtr: SENW Sec: 24 Twp: 33N Range: 10W Meridian: N
Latitude: 37.092304 Longitude: -107.888980

FACILITY - API Number: 05-067-00 Facility ID: 215160

Facility Name: CRAIG Number: 2E
Qtrqtr: SENW Sec: 24 Twp: 33N Range: 10W Meridian: N
Latitude: 37.092304 Longitude: -107.888980

CORRECTIVE ACTIIONS:

1 CA# 85880

Corrective Action: Remove oil and gas equipment from the project area. Date: 08/31/2017

Response: CA COMPLETED Date of Completion: 02/27/2018

Operator Comment: The meter house belongs to the landowner and is planned to be or is being utilized as a tool storage shed. BP has no authority to remove this shed as it is not BP property.

COGCC Decision:

COGCC
Representative:

2 CA# 85881

Corrective Action: Permanent stormwater controls need to be installed to stabilize the northwestern portion of the project area.

Date: 08/18/2017

Response: CA COMPLETED

Date of Completion: 07/09/2018

Operator Comment: After lengthy negotiations with the landowner they agreed to allow BP access to the property to install a rock rundown to slow the velocity of storm water on the northwestern corner of the well pad. BP has installed the BMP's authorized by the surface owner. BP no longer has access to this location without contacting the landowner and having them unlock the gate for BP or it's contractors. Landowner believes that the surface has been returned to them and they intend to utilize this land as an area for storage for their equipment and belongings as they see fit.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective Actions have been addressed to the best of BP's ability as the well was plugged and abandoned in 2013 and the surface owner has since removed the BP lock and BP can only access when landowner will agree to unlock the gate.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 7/24/2018 9:47:38 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
------------------------	--------------------

401711986	Work completion photos
-----------	------------------------

Total Attach: 1 Files