

Well Name : Bayfield Federal 2
API # : 067-09017



Photo 1: Wellhead sign.



Photo 2: Broken production tank.

Well Name : Bayfield Federal 2
API # : 067-09017



Photo 3: Unused pipe along fencing.



Photo 4: Blanket material on fill slope.

Well Name : Bayfield Federal 2
API # : 067-09017



Photo 5: Loose blanket material on fill slope .



Photo 6: Fill slope erosion on SE corner of location.