

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401730756

Date Received:

08/10/2018

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Tesla Dougherty

Phone

970-304-5245

Email

tesla.dougherty@nblenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682503607

Inspection Date: 07/17/2018

FIR Submit Date: 07/18/2018

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

LOCATION - Location ID: 329551

Location Name: RITER-64N64W Number: 18NWSE County: \_\_\_\_\_

Qtrqtr: NWSE Sec: 18 Twp: 4N Range: 64W Meridian: 6

Latitude: 40.310650 Longitude: -104.590440

FACILITY - API Number: 05-123-00 Facility ID: 329551

Facility Name: RITER-64N64W Number: 18NWSE

Qtrqtr: NWSE Sec: 18 Twp: 4N Range: 64W Meridian: 6

Latitude: 40.310650 Longitude: -104.590440

CORRECTIVE ACTIONS:

1 CA# 117525

Corrective Action: SEE "COGCC COMMENTS" FOR CORRECTIVE ACTIONS REGARDING FINAL RECLAMATION

Date: 08/03/2017

Response: CA COMPLETED

Date of Completion: 07/27/2018

Operator Comment: Noble had the location deep ripped and re-seeded. Mulch was added to mitigate potential weeds and stormwater concerns. The landowner requested an inter-seeding in September 2018.

COGCC Decision: Not Approved

COGCC Decision "Not Approved. Inspection #682503607 required operator to "Perform reclamation at the well

COGCC Representative:	<p>location in accordance to COGCC 1000 series rules and establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed. Revegetation activities shall be complete no later than 11/15/2017".</p> <p>Operator response of "Corrective Action Complete" is a notification to the COGCC that the corrective action has been addressed in its entirety. Operator states in comments that "landowner requested an inter-seeding in September 2018"; revegetation activities/seeding have not been completed per the corrective action. Corrective action has not been completed. This is being noted as a "falsified report or record"</p>
-----------------------	---

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tesla Dougherty

Signed: \_\_\_\_\_

Title: EHS Specialist

Date: 8/10/2018 1:53:02 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
-------------------------------	---------------------------

401730756	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files