

FORM  
6Rev  
05/18

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

401739625

Date Received:

## WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 51130

Contact Name: Michael Nicol

Name of Operator: LOCIN OIL CORPORATION

Phone: (281) 362-8600

Address: 2445 TECHNOLOGY FOREST BD #710

Fax: (281) 419.6626

City: THE WOODLANDS State: TX Zip: 77381

Email: mnicol@locinoil.com

For "Intent" 24 hour notice required,

Name:

Tel:

COGCC contact:

Email:

API Number 05-103-08222-00

Well Name: FORK UNIT-FEDERAL

Well Number: 14-11-1-2

Location: QtrQtr: SESW Section: 11 Township: 1S Range: 102W Meridian: 6

County: RIO BLANCO

Federal, Indian or State Lease Number: 44472

Field Name: DOUGLAS CREEK NORTH

Field Number: 17900

☐ Notice of Intent to Abandon☒ Subsequent Report of Abandonment

### Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.970833

Longitude: -108.814150

GPS Data:

Date of Measurement: 06/21/2011

PDOP Reading: 1.6

GPS Instrument Operator's Name: D. Estel

Reason for Abandonment:

☐ Dry☐ Production Sub-economic☐ Mechanical Problems☐ Other

Casing to be pulled:

☐ Yes☐ No

Estimated Depth:

Fish in Hole:

☐ Yes☐ No

If yes, explain details below

Wellbore has Uncemented Casing leaks:

☐ Yes☐ No

If yes, explain details below

Details:

### Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
MANCOS B	2302	2387	07/17/2018	CEMENT	2237

Total: 1 zone(s)

### Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	118	100	118	0	VISU
1ST	7+7/8	5+1/2	15.5	2,506	200	2,506	1,145	CALC

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIPB #2: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIPB #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set	20	sks cmt from	2149	ft. to	2237	ft.	Plug Type:	CASING	Plug Tagged:	<input checked="" type="checkbox"/>
Set	65	sks cmt from	1547	ft. to	2047	ft.	Plug Type:	CASING	Plug Tagged:	<input checked="" type="checkbox"/>
Set	65	sks cmt from	1481	ft. to	1530	ft.	Plug Type:	CASING	Plug Tagged:	<input checked="" type="checkbox"/>
Set	45	sks cmt from	267	ft. to	1465	ft.	Plug Type:	CASING	Plug Tagged:	<input checked="" type="checkbox"/>
Set	_____	sks cmt from	_____	ft. to	_____	ft.	Plug Type:	_____	Plug Tagged:	<input type="checkbox"/>

Perforate and squeeze at \_\_\_\_\_ 160 ft. with \_\_\_\_\_ 45 sacks. Leave at least 100 ft. in casing \_\_\_\_\_ 90 CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

(Cast Iron Cement Retainer Depth)

Set \_\_\_\_\_ sacks half in. half out surface casing from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Tagged: ☐

Set \_\_\_\_\_ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☒ No

Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: 100 ft. of 5+1/2 inch casing Plugging Date: 07/26/2018

\*Wireline Contractor: DLD Wiereline

\*Cementing Contractor: DUCO Inc.

Type of Cement and Additives Used: Class G cement

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

\*ATTACH JOB SUMMARY

Technical Detail/Comments:

Cut and pulled 100 feet 5-1/2" casing. Cement retainer (8-5/8") set at 90 feet. Squeeze 10 sacks below reteiner and fill 8-5/6" casing with 35 sacks 15.8 ppg Class G cement.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_

Print Name: Michael J Nicol

Title: Manager

Date: \_\_\_\_\_

Email: mnicol@locinoil.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: \_\_\_\_\_

Date: \_\_\_\_\_

### CONDITIONS OF APPROVAL, IF ANY:

#### COA Type

#### Description

--	--

### Attachment Check List

Att Doc Num

Name

401739693	WELLBORE DIAGRAM
401739698	CEMENT JOB SUMMARY

Total Attach: 2 Files

### General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	------------------------

Total: 0 comment(s)