

SURFACE CASING CHECK

Well Name Bernhardt O 12-19 (Noble)

☐ New Drill ☐ Refiling ☐ Deepen ☐ Re-Enter ☐ Recomplete and
Operate ☒ Plug and Abandon ☐ Casing Repair

SB5 Base of Fox Hills 114'

Cheyenne Basin Map Base of Fox Hills _____

Fox Hills Protection Area 5% Rule _____

Deepest Water Well w/in One Mile 198'

Operator-Proposed Surface Casing Depth _____

Actual Surface Casing Depth 565

Change Permit Surface Casing Depth from _____ to _____

OK on ☐ this well's or ☐ offset well's induction log at _____

No Sussex Production w/in 1 mile