

SURFACE CASING CHECK

Well Name Harsh H 26-10

☐ New Drill ☐ Refiling ☐ Deepen ☐ Re-Enter ☐ Recomplete and
Operate ☒ Plug and Abandon ☐ Casing Repair 123-29677

SB5 Base of Fox Hills 612'

Cheyenne Basin Map Base of Fox Hills _____

Fox Hills Protection Area 5% Rule _____

Deepest Water Well w/in One Mile 600'

Operator-Proposed Surface Casing Depth _____

Actual Surface Casing Depth 700'

Change Permit Surface Casing Depth from _____ to _____

OK on ☐ this well's or ☐ offset well's induction log at _____

Sussex Production w/in 1 mile

OK