

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/04/2018

Submitted Date:

09/05/2018

Document Number:

688500083**FIELD INSPECTION FORM**Loc ID 319709 Inspector Name: CANFIELD, CHRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10454Name of Operator: PETROSHARE CORPORATIONAddress: 9635 MAROON CIRCLE #400City: ENGLEWOOD State: CO Zip: 80112**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments5 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Brown, Devin	(303)-349-0302	dbrown@petrosharecorp.com	Production Ops Manager
Axelson, John		john.axelson@state.co.us	
Lloyd, Bill		blloyd@petrosharecorp.com	Operations Manager

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201052	WELL	SI	06/01/2017	OW	001-06455	STATE OF COLORADO AB 1	SI
319709	LOCATION	AC			-	STATE OF COLORADO AB-62S66W 16NESE	EI
445292	TANK BATTERY	AC	03/30/2016		-	State of Colorado AB Tank Battery	EI
446568	SPILL OR RELEASE	CL	07/04/2016		-	SPILL/RELEASE POINT	EI

General Comment:

Inspection of Location 319709 to gauge progress on REM 11710 and REM 11714 as well as corrective actions identified in Field Inspection Form 688500079.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds		
Corrective Action:	Comply with Rule 603.f	Date:	09/07/2018
Type			
Comment:			
Corrective Action:		Date:	
Type	STORAGE OF SUPL		
Comment:	Unused equipment being kept on the location.		
Corrective Action:	Comply with Rule 603.f	Date:	09/21/2018

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Perimeter fence has been removed from the south side of the location.		
Corrective Action:	Fencing is required to restrict access by unauthorized persons.	Date:	08/31/2018
Type	OTHER		
Comment:	Open excavations without temporary safety fencing.		
Corrective Action:	Per Rule 605.c, temporary safety fencing is required to protect public safety.	Date:	08/31/2018

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Location Construction

Location ID: 319709 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:**Comment:** _____

Corrective Action: _____

Date: _____

Wildlife BMPs:**Comment:** _____

Corrective Action: _____

Date: _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
WADDLES	No		

Comments: Erosion BMPs: Spoil piles without storm-water BMPs

Other BMPs: _____

Corrective Action: Install storm-water BMPs as required by Rule 1002.f.

Date: 08/31/2018

Comment: _____**Corrective Action:** _____

Date: _____

On Site Inspection (305):Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: <u>201052</u>	Type: <u>WELL</u>	API Number: <u>001-06455</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Facility ID: <u>319709</u>	Type: <u>LOCATION</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EI</u>
Facility ID: <u>445292</u>	Type: <u>TANK</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EI</u>
Facility ID: <u>446568</u>	Type: <u>SPILL OR</u>	API Number: <u>-</u>	Status: <u>CL</u>	Insp. Status: <u>EI</u>

COGCC Comments

Comment	User	Date
Missed corrective action deadlines (see Field Inspection 688500079) for temporary safety fencing and storm-water BMPs.	canfielc	09/05/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688500084	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4570338