

SURFACE CASING CHECK

Well Name HSR Foster 3-35 (woble)

#123-19006

New Drill Refiling Deepen Re-Enter Recomplete and Operate Plug and Abandon Casing Repair

SB5 Base of Fox Hills ~~49~~ 605'

Cheyenne Basin Map Base of Fox Hills _____

Fox Hills Protection Area 5% Rule _____

Deepest Water Well w/in One Mile 440'

Operator-Proposed Surface Casing Depth _____

Actual Surface Casing Depth 739

Change Permit Surface Casing Depth from _____ to _____

OK on this well's or offset well's induction log at _____

Sussex Production w/in 1 mile

ok