

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/12/2018

Submitted Date:

09/13/2018

Document Number:

691300508**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
 318981 \_\_\_\_\_ Kraich, Adam \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCInspections@extracti onog.com	<a href="#">All Inspections</a>
Adamczyk, Megan		megan.adamczyk@state.co.u s	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
455996	WELL	DG	08/08/2018		123-47319	Rinn Valley East N17-20-6N	DG

**General Comment:**

**Inspected Facilities**Facility ID: 455996 Type: WELL API Number: 123-47319 Status: DG Insp. Status: DG**Complaint**Comment: Inspection in response to complaint. 18#200446244Field Inspector Assigned: Adam KraichComplaint Received:Date: 9-12-2018Complaint Contacted:Date: 9-12-2018 @12:54 left VM, no callbackLocation #: 318981Inspection Document #: 691300508Nature of complaint: OdorField Inspector Actions:On 9-12-2018, I received a complaint in regard to odor coming from the Rinn Valley East location owned and operated by Extraction Oil & Gas.On 9-12-2018, I performed a location inspection. Upon arrival I stopped by the complainant's property as it was on the way into the drill pad (approximately 1170' north of the drill pad). I did in fact experience odors consistent with oil based drilling mud (OBM). I visited the location immediately afterward and spoke to rig management. I informed them of the issue, and they will be taking actions to mitigate off location odors.I have issued a corrective action under rule 805.bAll information reviewed and site inspection information were submitted to the complaint specialist for further review.Corrective Action: Odor observed by COGCC staff related to referenced oil and gas location, actions must be taken to stop the odor per Rule 805.b. Additionally, this matter has been referred to the CDPHE for possible further investigation.Date: 09/14/2018**Well Drilling****Rig:** Rig Name: Patterson 901 Pusher/Rig Manager: Manny  
Permit Posted: Yes Access Sign: Yes**Well Control Equipment:**Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_**Drill Fluids Management:**Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_Comment: Inspection in response to complaint

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691300509	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4578033">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4578033</a>