

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401688507  
Date Received:  
06/28/2018

## FIR RESOLUTION FORM

### CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name	Phone	Email
Beebe, Sabre		<a href="mailto:SanJuanCOGCC@bp.com">SanJuanCOGCC@bp.com</a> <a href="mailto:Sabre.Beebe@bp.com">Sabre.Beebe@bp.com</a>

### COGCC INSPECTION SUMMARY:

FIR Document Number: 680602409  
Inspection Date: 01/04/2018 FIR Submit Date: 01/12/2018 FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303

### LOCATION - Location ID: 307006

Location Name: MAYFIELD GU A-M34N8W Number: 10SWSW County: LA PLATA  
Qtrqr: SWS Sec: 10 Twp: 34N Range: 8W Meridian: M  
Latitude: 37.201641 Longitude: -107.709667

### FACILITY - API Number: 05-067- -00 Facility ID: 294126

Facility Name: MAYFIELD A Number: 3  
Qtrqr: SWS Sec: 10 Twp: 34N Range: 8W Meridian: M  
Latitude: 37.201641 Longitude: -107.709667

### CORRECTIVE ACTIONS:

1 ☒ CA# 113916

Corrective Action: Document established, desirable, vegetative cover to COGCC interim reclamation standards, or re-seed the southern portion of the project area by the end of the fall seeding window, November 1, 2018. Weeds need to be controlled at this appropriate time but no later than June 15, 2018.

Date: 11/01/2018

Response: CA COMPLETED Date of Completion: 05/05/2018

Seeding has been performed on this location at the same time as work performed on the Mayfield A1 see

Operator  
Comment: attached photos

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 113917

Corrective Action: Stormwater controls need to be installed to stabilize stormwater run-on and run-off from the project area.

Date: 02/28/2018

Response: CA COMPLETED

Date of Completion: 05/05/2018

Operator  
Comment: Storm water issues have been addressed on this location see attached.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions addressed on the Mayfield A1 and A3 at the same time see attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: \_\_\_\_\_

Title: Compliance Specialist

Date: 6/28/2018 11:41:22 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401688507	FIR RESOLUTION SUBMITTED
401688519	CA completion photos

Total Attach: 2 Files