

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401768655

Date Received:

09/19/2018

FIR RESOLUTION FORM

Overall Status: FRQ

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

0 CA Completed
2 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 1099 18TH ST STE 2300

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Singer, Sheila

ssinger@hpres.com

BARBER, MATT

mbarber@hpres.com

Axelson, John

john.axelson@state.co.us

Enforcement, COGCC

dnr_cogccenforcement@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 672200071

Inspection Date: 09/14/2018

FIR Submit Date: 09/18/2018

FIR Status: _____

Inspected Operator Information:

Company Name: HIGHPOINT OPERATING CORPORATION

Company Number: 10071

Address: 1099 18TH ST STE 2300

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: _____

Location Name: _____ Number: _____ County: _____

Qtrqr: NWNE Sec: 29 Twp: 5N Range: 61W Meridian: 6

Latitude: 40.378286 Longitude: -104.228297

FACILITY - API Number: 05-123- -00 Facility ID: 448950

Facility Name: SANDY HILL Number: 5-61-29

Qtrqr: NWNE Sec: 29 Twp: 5N Range: 61W Meridian: 6

Latitude: 40.378286 Longitude: -104.228297

CORRECTIVE ACTIONS:

1 CA# 118787

Corrective Action: Consult with both landowners regarding cleanup and ensure compliance with COGCC Table 910-1. Provide analytical data, a site map, and manifests (if needed) on supplemental Form 27. Incorporate remediation plans into existing Remediation Project 11244 and report remediation progress using eForm 27.

Date: 07/31/2018

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: Offsetting landowner will not grant permission to cleanup drill cuttings and remediation.

COGCC Decision:

COGCC Representative:

2 CA# 118788

Corrective Action: Comply with Rule 603.f .

Date: 09/09/2018

Response: FACTUAL REVIEW REQUEST

Basis for Review: CA dates are not per the guidelines

Operator Comment: Offsetting landowner will not grant permission to cleanup drill cuttings and remediation.

COGCC Decision:

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Matt Barber

Signed:

Title: Sr. Regulatory Specialist

Date: 9/19/2018 5:04:29 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files