

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/05/2018

Submitted Date:

09/17/2018

Document Number:

682503851

FIELD INSPECTION FORM

Loc ID 447525 Inspector Name: Trujillo, Aaron On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		jsauer@foundationenergy.com	
		denise.arthur@state.co.us	
		abeard@foundationenergy.com	
		regulatory@foundationenergy.com	
		dnr_cogccenforcement@state.co.us	

General Comment:

This is a follow-up reclamation and good housekeeping inspection.

The following comment is copied from inspection #682503491, please see FIR for additional details:

Complainant contacted Reclamation staff on 6/12/2018 in regards to noxious weed concerns on Foundation Locations and submitted complaint doc. #200445970 stating that "Diffuse Knapweed has returned to both locations" on 6/13/2018. The locations in reference are the Krager TB / well location and the SOONER SE SEC 21 TB location, both of which past complaints regarding noxious weed concerns (see inspection #682401201 and inspection #682401240).

On 6/13/2018 at 15:09, upon receiving a formal complaint, Reclamation Specialist Trujillo contacted complainant via phone to discuss concerns. Complainant stated that operator has failed to perform weed management, and weeds (Diffuse Knapweed) has continued to grow and spread from the location onto their property.

See "Good Housekeeping".

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	<p>Inspection #682503491 documented that Diffuse Knapweed (<i>Centaurea diffusa</i>) has continued to establish on the location and access road and is beginning to encroach onto the adjacent lands. Inspection required operator to properly remove and control noxious weeds on location Operator submitted resolution #401681739 indicating weeds were sprayed. Follow-up inspection #682503561 on 7/11/2018 documented that maturing Noxious weeds remain on location.</p> <p>Operator has failed to conduct sufficient, ongoing weed management. Corrective action required ongoing weed management and for operator to remove and control noxious weeds on location and adjacent lands. Diffuse Knapweed remains evident on location</p>		
Corrective Action:	<p>Properly remove and control noxious weeds on location. Properly manage and remove noxious weeds from the adjacent lands that have encroached from Foundations location. Ongoing weed management and monitoring is required, and needs to occur in accordance to COGCC rules and regulations. Due to the significant nature, extent, or duration of this alleged rule violation immediate referral to enforcement is required and a corrective action date will not be applied.</p>		Date:

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

COGCC Comments

Comment	User	Date
On 8/3/2018, COGCC Field Inspector Evans contacted Reclamation Specialist Trujillo regarding weed issues. Evans stated that the Complainant was on location and made contact with him. Complainant indicated that sufficient weed management has not been conducted and that noxious weed issues remained.	trujilloam	09/07/2018
On 9/2/2018 Complainant contacted COGCC staff indicating locations have not received proper "good housekeeping". Complainant indicated that she personally bagged "21 garbage sacks of diffuse knapweed from this area".		

Operator is directed to perform corrective actions outlined on this inspection report immediately. Doing so may decrease the duration of the alleged violations and the penalties that may be assessed pursuant to Rule 523.

trujilloam

09/07/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401765675	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4581124
682503852	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4581121