

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401772019

Date Received:

09/24/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10409

Name of Operator: PEAKVIEW OPERATING COMPANY LLC

Address: 707 SEVENTEENTH ST STE 4200

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Wise, Wayne

720-402-3085

wwise@peakviewenergy.com

Walters, Steve

720-402-3081

swalters@peakviewenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689801297

Inspection Date: 06/25/2018

FIR Submit Date: 06/26/2018

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: PEAKVIEW OPERATING COMPANY LLC

Company Number: 10409

Address: 707 SEVENTEENTH ST STE 4200

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 316747

Location Name: GRASSY CREEK COAL CO-66N87W Number: 26NWSE County: ROUTT

Qtrqtr: NWSE Sec: 26 Twp: 6N Range: 87W Meridian: 6

Latitude: 40.446149 Longitude: -107.114752

FACILITY - API Number: 05-107-00 Facility ID: 232620

Facility Name: GRASSY CREEK COAL CO Number: 2

Qtrqtr: NWSE Sec: 26 Twp: 6N Range: 87W Meridian: 6

Latitude: 40.446149 Longitude: -107.114752

CORRECTIVE ACTIONS:

1 CA# 117012

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 07/26/2018

Response: CA COMPLETED

Date of Completion: 07/28/2018

Stained soil around pumping unit engine and exhaust pipe, was removed and remediated. Leaking engine

Operator: lubricator was repaired. Stained soil left from hot oiling operations was removed and area remediated.  
Comment: Work was started Monday July 23 2018 and completed Saturday July 28 2018.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

--

OPERATOR COMMENT AND SUBMITTAL

Comment: Stained soil was removed and remediated. Clean gravel was placed around pumping unit base and engine area. Loose screws on engine lubricator were sealed and tightened.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Wayne Wise

Signed: \_\_\_\_\_

Title: Operations Engineer

Date: 9/24/2018 10:02:55 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files