

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401768833  
Date Received:  
09/20/2018

FIR RESOLUTION FORM

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-3779  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Luke Reddy	970-515-1292	luke.reddy@anadarko.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682403952  
Inspection Date: 08/31/2018 FIR Submit Date: 09/04/2018 FIR Status:

Inspected Operator Information:

Company Name: KERR MCGEE OIL & GAS ONSHORE LP Company Number: 47120  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-3779

LOCATION - Location ID: 448107

Location Name: SHARON Number: 11-21HZ County:  
Qtrqr: NESW Sec: 21 Twp: 4N Range: 67W Meridian: 6  
Latitude: 40.297581 Longitude: -104.897599

FACILITY - API Number: 05-123-00 Facility ID: 448107

Facility Name: SHARON Number: 11-21HZ  
Qtrqr: NESW Sec: 21 Twp: 4N Range: 67W Meridian: 6  
Latitude: 40.297581 Longitude: -104.897599

CORRECTIVE ACTIONS:

1 ☒ CA# 118406

Corrective Action: Stabilize topsoil immediately per Rule 1002.c. The corrective date is not intended to be the date for which the Operator needs to complete the corrective action but rather the date the location was observed out of compliance.

Date: 08/31/2018

Response: CA COMPLETED Date of Completion: 09/20/2018

Operator Comment: Topsoil pile has been stabilized.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

2 ☒ CA# 118407

Corrective Action: Install or repair required BMPs per Rule 1002.f. The corrective date is not intended to be the date for which the Operator needs to complete the corrective action but rather the date the location was observed out of compliance.

Date: 08/31/2018

Response: CA COMPLETED

Date of Completion: 09/20/2018

Operator Comment: Sediment traps have been lined. Sediment traps had to be moved to better suit the location layout and were in process of being completed at time of inspection.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Topsoil pile has been stabilized.  
Sediment traps have been lined. Sediment traps had to be moved to better suit the location layout and were in process of being completed at time of inspection.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Luke Reddy

Signed: \_\_\_\_\_

Title: Regulatory Specialist

Date: 9/20/2018 8:50:11 AM

#### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401768833	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files