

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/14/2018

Submitted Date:

09/18/2018

Document Number:

672200074**FIELD INSPECTION FORM**Loc ID 311326 Inspector Name: Graber, Candice (Nikki) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Evans, Jacob	303-328-5605	jacob.evans@nblenergy.com	Noble Environmental
Oakman, Kari		kari.oakman@state.co.us	
Axelson, John		john.axelson@state.co.us	
,		NBL_DJBU_Inspections@NB LENERGY.COM	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451222	SPILL OR RELEASE	CL			-	SPILL/RELEASE POINT	EI

General Comment:

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.
Photos attached to document site condition at the time of inspection.

COGCC field follow up to REM 10589.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	Excavated area not stabilized, weeds present.		
Corrective Action:	Comply with Rule 603.f; stabilize area and control weeds until final reclamation is completed	Date:	10/14/2018
Type	UNUSED EQUIPMENT		
Comment:	Remove unused produced water vault under an approved Form 27.		
Corrective Action:	Comply with Rule 603.f . Submit a Form 27 for prior approval before removing vault.	Date:	12/16/2018
Type	UNUSED EQUIPMENT		
Comment:	Remove unused equipment from location.		
Corrective Action:	Comply with Rule 603.f .	Date:	12/16/2018

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Spill/Remediation:**Comment: [Groundwater monitoring wells have been installed and are limited to the excavation area.](#)Corrective Action: [Operator shall install additional groundwater monitoring wells outside of the excavation area, in native soils to confirm point of compliance. If impacts are discovered additional monitoring wells may be required. Installation of monitoring well\(s\) shall be completed in time for fourth quarter 2018 sampling.](#)

Date: 12/16/2018

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

COGCC Comments

Comment	User	Date
Stabilize disturbed areas from remediation and install stormwater BMPs until final reclamation is completed.	graberc	09/18/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401767269	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4582293
672200076	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4582283