

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/09/2018

Submitted Date:

09/25/2018

Document Number:

672200080**FIELD INSPECTION FORM**Loc ID 322916 Inspector Name: Graber, Candice (Nikki) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Oakman, Kari		kari.oakman@state.co.us	
Evans, Jacob	303-328-5605	jacob.evans@nblenergy.com	Noble Environmental
,		NBL_DJBU_Inspections@NB LENERGY.COM	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
455923	SPILL OR RELEASE	AC	07/17/2018		-	Bacon 3 flowline	EI

**General Comment:**

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.  
Photos attached to document site condition at the time of inspection.



**Environmental****Spill/Remediation:**

Comment: COGCC Inspection in response to spill 401700100. Spill excavation area has been backfilled and groundwater monitoring array has been installed.

Corrective Action:

The Operator shall submit a Form 27 Site Investigation and Remediation Workplan for the investigation and remediation of impacts to ground water in accordance with Rule 909.c. The Form 27 Workplan may be submitted with the excavation and site assessment results, but should be submitted no later than 90 days from the Spill Report Date in order to resolve this release.

Date: 10/09/2018

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
No surface reclamation of spill area has been performed. Operator shall reclaim disturbed area in accordance with 1000 series rules.	graberc	09/21/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
672200082	Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4587626">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4587626</a>