

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401758424
Date Received:
09/10/2018

FIR RESOLUTION FORM

CA Summary:
2 of 2 CAs from the FIR responded to on this Form
2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96155
Name of Operator: WHITING OIL & GAS CORPORATION
Address: 1700 BROADWAY STE 2300
City: DENVER State: CO Zip: 80290
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name Phone Email
Kyle Waggoner 4326616647 kyle.waggoner@whiting.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682503794
Inspection Date: 08/29/2018 FIR Submit Date: 08/31/2018 FIR Status:

Inspected Operator Information:

Company Name: WHITING OIL & GAS CORPORATION Company Number: 96155
Address: 1700 BROADWAY STE 2300
City: DENVER State: CO Zip: 80290

LOCATION - Location ID: 436874

Location Name: Razor Number: 33O Pad County:
Qtrqr: SWSE Sec: 33 Twp: 10N Range: 58W Meridian: 6
Latitude: 40.788564 Longitude: -103.867492

FACILITY - API Number: 05-123-00 Facility ID: 436874

Facility Name: Razor Number: 33O Pad
Qtrqr: SWSE Sec: 33 Twp: 10N Range: 58W Meridian: 6
Latitude: 40.788564 Longitude: -103.867492

CORRECTIVE ACTIONS:

1 CA# 118348
Corrective Action: Repair or install berms Date: 09/17/2018

Response: CA COMPLETED Date of Completion: 09/07/2018

Operator Comment: The berms have been repaired.

COGCC Decision: Approved pending re-inspection

Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an

COGCC Representative: acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

2 CA# 118349

Corrective Action: Provide COGCC with the drilling and fracking schedule for the additional wells by 9/14/2018. All areas of the location not reasonably needed for production will require stabilization in accordance with 1003 reclamation rules until interim reclamation is conducted by 10/1/2018

Date: 09/14/2018

Response: CA COMPLETED

Date of Completion: 09/10/2018

Operator Comment: We currently do not have any drilling or fracking activities scheduled for this area. We are requesting a factual review of the interim reclamation acreage. According to our records, the approved Form 2A has an interim reclamation of 3.4 acres and it has been reclaimed to 1.3 acres. In addition, this remaining area is needed for future workover, maintenance, truck access, and production activities.

COGCC Decision: Approved pending re-inspection

COGCC Representative: COGCC held meeting with Whiting on 9/25/2018 to discuss location and concerns. Areas of the location identified in report will require stabilization.

OPERATOR COMMENT AND SUBMITTAL

Comment:

[Empty text box for operator comment]

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Kyle Waggoner

Signed:

Title: Field Regulatory Manager

Date: 9/10/2018 3:13:27 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
401758424	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files