

Inspection Photos  
Location Name: Federal-Chamberlin 22-1  
API: 05-081-06021



**Photo 1. Overview of location taken at entrance facing northeast.**



**Photo 2. Landfarm area with fresh additions.**

Inspection Photos  
Location Name: Federal-Chamberlin 22-1  
API: 05-081-06021



**Photo 3. 2 unmarked risers adjacent to separator.**



**Photo 4. Separator less than 50 feet from fired tanks.**