

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/26/2018

Submitted Date:

10/02/2018

Document Number:

682404010**FIELD INSPECTION FORM**Loc ID 438066 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10611Name of Operator: LONGS PEAK RESOURCES LLCAddress: 2323 S SHEPHERD SUITE 1150City: HOUSTON State: TX Zip: 77019**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
GEISER, EDWARD	(713) 335-4730	egeiser@juncap.com	
Clarkson, David		dclarkson@vrtxep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438066	LOCATION	AC			-	RAILAY 28-3-1CH	RI

General Comment:

This is a follow-up Interim Reclamation and Stormwater inspection to Field Inspection Report Document #682403425. Any corrective actions from previous inspections that have not been addressed are still applicable.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	Weedy, annual vegetation (Russian thistle) was observed throughout portions of the interim reclamation area. Refer to the attached inspections photos.		
Corrective Action:	Comply with Rule 603.f. to control and manage weedy, annual vegetation to prevent weed waste and prevent spread of dispersing seeds onto adjacent lands.		Date: 10/16/2018

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? In Production areas stabilized ?

1003c. Compacted areas have been cross ripped?

1003d. Drilling pit closed? Subsidence over on drill pit?

Cuttings management:

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In

Production areas have been stabilized? Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATIONCropland

Top soil replaced Recontoured Perennial forage re-established

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation In

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA%

TRANSECT RESULTS OF REFERENCE AREA%

TOTAL % OF DESIRABLE VEGETATION COVER

VEGETATIVE COVER

1003 f. Weeds Noxious weeds?

Comment Germination of desirable species was observed. Some areas were observed with little to no germination which may require additional work if no progress is observed in the future. Operator shall continue to monitor and manage this site until the location meets Rule 1003 standards, including weed management. A follow-up inspection will occur to ensure compliance with Rule 1003 standards.

Corrective Action Date

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: Date Final Reclamation Completed:

Final Land Use: RANGELAND

Reminder:

Comment:

Well plugged Pit mouse/rat holes, cellars backfilled

Debris removed No disturbance /Location never built

Access Roads Regraded Contoured Culverts removed

Gravel removed

Location and associated production facilities reclaimed Locations, facilities, roads, recontoured

Compaction alleviation Dust and erosion control

Non cropland: Revegetated 80% Cropland: perennial forage

Weeds present Subsidence

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA%

TRANSECT RESULTS OF REFERENCE AREA%

TOTAL % OF DESIRABLE VEGETATION COVER

VEGETATIVE COVER

Comment:

Corrective Action:	Date
Overall Final Reclamation	Well Release on Active Location <input type="checkbox"/> Multi-Well Location <input type="checkbox"/>

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps	Fail					

Comment: Stormwater BMP maintenance is required as the sediment trap is not in proper functioning condition.

Rill erosion forming along the southern fill slope.

Date: 10/30/2018

Corrective Action: Install or repair required BMPs in accordance with good engineering practices per Rule 1002.f.

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401782133	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4595870
682404012	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4595862