

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401781783

Date Received:

10/02/2018

## FIR RESOLUTION FORM

### CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10665

Name of Operator: CCRP OPERATING INC

Address: 717 17TH STREET STE 1525

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Ryan Zorn

720-961-4785

rz@clearcreekrp.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 682404008

Inspection Date: 09/26/2018

FIR Submit Date: 09/26/2018

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: CCRP OPERATING INC

Company Number: 10665

Address: 717 17TH STREET STE 1525

City: DENVER State: CO Zip: 80202

### LOCATION - Location ID: 456179

Location Name: True Ranch Fee Number: 2326 East County: \_\_\_\_\_

Qtrqr: NENE Sec: 23 Twp: 12N Range: 65W Meridian: 6

Latitude: 40.998720 Longitude: -104.623110

### FACILITY - API Number: 05-123-00 Facility ID: 456179

Facility Name: True Ranch Fee Number: 2326 East

Qtrqr: NENE Sec: 23 Twp: 12N Range: 65W Meridian: 6

Latitude: 40.998720 Longitude: -104.623110

### CORRECTIVE ACTIONS:

1 ☒ CA# 119027

Corrective Action: Install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices. Corrective action date is being back dated to when stormwater BMPs should have been installed.

Date: 09/20/2018

Response: CA COMPLETED

Date of Completion: 09/27/2018

Operator Comment: Operator has installed required BMP (Silt Fence) on 9/27/2018 per Rule 1002.f in accordance with good engineering practices.

COGCC Decision: Approved via an AMI

COGCC Representative: This is an acknowledgement that the document was received. Based on the attached photo and report, it appears the Operator installed a perimeter BMP (silt fence) per the previous corrective action.

BMPs shall be selected based on site-specific conditions, such as slope, soil type, vegetation cover, and proximity to water bodies, and may include maintaining in-place some or all of the construction BMPs until the Location is abandoned and final reclamation is achieved pursuant to Rule 1004.

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Operator has attached photo of Silt Fence in addition to daily construction report for 9/27/2018 documenting installation of Silt Fence.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ian Myers

Signed: \_\_\_\_\_

Title: VP-Operations

Date: 10/2/2018 2:47:43 PM

#### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401781783	FIR RESOLUTION SUBMITTED
401781934	Construction Report
401781938	Silt Fence Photo

Total Attach: 3 Files