

COLORADO



99999999

ATION COMMISSION
REPORT

Historical

- ☒ NOTICE OF UNSATISFACTORY INSPECTION
☐ NOTICE OF SATISFACTORY INSPECTION

1120 Lincoln Street, Suite 801
Denver, CO 80203
(303)894-2100



API No. 05- <i>121 - (0-2100) 07086</i>	LEASE NAME: <i>Rediers #4</i>
LOCATION: <i>NW50 2-2N-54</i>	OPERATOR: <i>? Xenia Unit / Energy S.</i>
DATE: <i>3-6-97</i>	INSPECTOR: <i>EBB</i>
Insp. Type: <i>HR</i> Insp. Status: <i>DA</i> PA: Y <input checked="" type="radio"/> N <input type="radio"/>	Pass/Fail: P <input type="radio"/> F <input checked="" type="radio"/> Viol.: Y <input checked="" type="radio"/> N <input type="radio"/> NOV: Y <input checked="" type="radio"/> N <input type="radio"/>

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210, 604.c(4))	<i>Gene Mitchell - handwritten</i>	
Pits (Reserve/Production) (Rule 902, 903, 904, 905)		
Fences (Rule 603.b.7, 604.C.(3), 1002.A)		
Tank Battery Equipment (Rule 603.b.3, 604)		
Fire Walls/Berms/Dikes (Rule 603.b.12, 604)		
General Housekeeping (Rule 603)		
Spills (Oil/Water) (Rule 907)		
Bradenhead (Rule 207.b)		
Drilling Well/Workover (Rule 317)		
Surface Rehabilitation (Rule 1002, 1003, 1004, 1103)	<i>bare spot at old site needs reseeding. Grass & sage.</i>	
Miscellaneous		



00064909

CORRECTIVE ACTION REQUIRED: *Reseed site, crimp straw to hold sand.*

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

RECEIVED

APR 11 6 1997