



LANDOWNER PERMISSION(SR)



02496522

CONSERVATION COMMISSION

NORTHEAST REGION FIELD INSPECTION REPORT



NOTICE OF UNSATISFACTORY INSPECTION
NOTICE OF SATISFACTORY INSPECTION

337 Cambridge
Brush, CO 80723 970-842-4465

Date: 9-15-01 Facility ID: Operator: ERF

Location: NESW 2-2N-54W Lease Name: Redios-3

API Number: 05-121-07102 Inspector: ED BINKLEY Cell: 970-380-2683

INSP TYPE SR INSP STATUS AA RECLAM PASS INTER PASS/FAIL P F VIOLATION Y N NOV Y N

UIC VIOL TYPE: UA MI OP PA OT TBG/PKR LK CSG LK ALL UIC VIOLATIONS REQUIRE NOAVS

Well ID Signs (Rule 210) Y N Comments:

Fences Y N (Rule 603.b.(7), 1002.a) Comments:

Production Pits (Rule 902, 903, 904) EARTHEN PITS ONLY SENSITIVE AREA YES NO

Produced Water Pits Total # Oil Accumulation? YES NO
Skimming/Settling Pits Total # Covered # Uncovered #
Special Purpose Pits Total # Lined # Unlined #

Tank Battery Equipment (Rule 604) BURIED OR PARTIALLY BURIED VESSELS: #STEEL #FIBERGLASS #CONCRETE #OTHER

Fire Walls/Berms/Dikes [Rule 604.a.(4)]

General Housekeeping (Rule 603.g)

Spills (Oil/Water) (Rule 906)

UIC Routine Inspection FILL OUT FORM 21 WHEN WITNESSING MIT Inj. Pressure Psig COMMENTS T-C Ann. Pressure Psig

Drilling Well/Workover (Rule 317)

Surface Rehabilitation (Rule 1003, 1004) Diamond Tail Ranch

Miscellaneous Landowner permission for plugging operation burial of cement and respiration of Tressa-Suebeck

CORRECTIVE ACTION REQUIRED: Date Corrective Action Required By: Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.