

\*\* COLORADO OIL & GAS INFORMATION MGMT SYSTEM \*\*  
 FIELD INSPECTIONS / SPILLS MAINTENANCE - ADD MODE

C01IN

API NUMBER	STAT/DATE	COUNTY	CURRENT OPERATOR
057 06368 1	AL 62695	JACKSON	10155 BRIGHT & COMPANY
	LOCATION		WELL NUMBER LEASE NAME
	SWNE 35 11.0 N 80.0 W 6		35-1 FISCHER DRAW UNIT FED
	FIELD 24010 FISCHER DRAW		FORM NBRR NIOBRARA

INSPDT	TYP	IS	PA	P/F	VIOL	SNC	RESPONSIBLE OPERATOR
08061999	I	AL	Y	P	N		10155 BRIGHT & COMPANY
	TYPE OF INSPECTION		TYPE OF COMPLAINT		AMT OF SPILL/RELEASE		
	HR				BO BW		
SCHEDULED	INSPECTORS NAME		REMEDY REQUIRED		PROBLEMS REMEDIED		MODIFIED
00000000	SHELTON		00000000		00000000		081399

NO DISTURBANCE, GRASSLAND



02496518

ENTER DATA - PRESS RETURN TO ADD OR PF 16 TO EXIT

\*\* COLORADO OIL & GAS INFORMATION MGMT SYSTEM \*\*  
 FIELD INSPECTIONS / SPILLS MAINTENANCE - ADD MODE C01IN

API NUMBER	STAT/DATE	COUNTY	CURRENT OPERATOR	
057-06368 0	AL 62695	JACKSON	10155 BRIGHT & COMPANY	
	LOCATION		WELL NUMBER	LEASE NAME
	SWNE 35 11.0 N 80.0 W 6		35-1	FISCHER DRAW UNIT FED
	FIELD 24010 FISCHER DRAW		FORM LKTA	LAKOTA

  

INSPDT	TYP	IS	PA	P/F	VIOL	SNC	RESPONSIBLE OPERATOR
08061999	I	AL	Y	P	N		10155 BRIGHT & COMPANY
	TYPE OF INSPECTION		TYPE OF COMPLAINT		AMT OF SPILL/RELEASE		
	HR				BO BW		
SCHEDULED	INSPECTORS NAME		REMEDY REQUIRED		PROBLEMS REMEDIED		MODIFIED
00000000	SHELTON		00000000		00000000		081399

NO DISTURBANCE, GRASSLAND

---

ENTER DATA - PRESS RETURN TO ADD OR PF 16 TO EXIT