

HILL RANCH 28-10 API # 05-071-06200 & HR 28-10V API # 05-071-07022 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: OCTOBER 25, 2018  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 687903213



THE ORIGINAL LOCATION SIGN FOR HILL RANCH 28-10 WAS ON A PORTABLE STAND IN FRONT OF THE WELL HEAD. THE SIGN WAS REMOVED FOR WELL SERVICE. TIMBER CREEK CAN NOT LOCATE THE SIGN AND WILL ORDER A NEW ONE. FOR NOW, THE WELL INFORMATION WAS WRITTEN ON THE DOOR OF THE SEPARATOR.

HILL RANCH 28-10 API # 05-071-06200 & HR 28-10V API # 05-071-07022 – TIMBER CREEK  
OGCC OPERATOR NUMBER 10672 - DATE: OCTOBER 25, 2018  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 687903213



A NEW MARKER WAS INSTALLED ON THE UNMARKED DEADMAN ANCHOR IN COMPLIANCE WITH RULE 604.c.Q.