

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/18/2018

Submitted Date:

10/19/2018

Document Number:

688400459

FIELD INSPECTION FORM

Loc ID 320400 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10548
Name of Operator: HRM RESOURCES II LLC
Address: 410 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 12 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Pape, Terry	(970) 768-5700	tpape@hrmres.com	VP Operations
Payne, Gina	303-893-6621	gpayne@hrmres.com	All inspections 5/31/17
Gomez, Jason		jason.gomez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203641	WELL	PR	07/07/1994	GW	001-09201	UPV 7-15N3	PR

General Comment:

[Edited 10/22/2018: Emergency Contact Number Corrective Action removed- Conor Pesicka](#)

Location

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:

Emergency Contact Number:		
Comment:	Sign and ECN on location is for HRM.	
Corrective Action:		Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	ECD had a pilot failure not burning		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: <u>10/19/2018</u>
Type	OTHER		
Comment:	Stained soil load out line to crude oil tank		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e		Date: <u>11/19/2018</u>

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER			,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	40BBL	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with crude oil tank			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 203641 Type: WELL API Number: 001-09201 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
AT time of inspection ECD had a pilot failure and was not lit. Called operator on sign (HRM) was told that they sold this well. operator gave me number of new operator P3. Got in contact with P3 Frank Bair, he said he would send someone to fix ECD .	silverr	10/19/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401803532	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4615815
688400472	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4615808