

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/15/2018

Submitted Date:

11/16/2018

Document Number:

689302361**FIELD INSPECTION FORM**Loc ID 334616 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccenforcement@state.co.us	<a href="#">Code Enforcement</a>
Elsener,		COGCC.inspections@caerusoilandgas.com	<a href="#">all Piceance inspections</a>
,		dnr_COGCCEngineering@state.co.us	<a href="#">Engineering</a>
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258802	WELL	PR	06/01/2002	GW	045-07657	ROSE RANCH 22-8 (G22)	TA

**General Comment:**

10 day MIT notification recieved. Document #401820708. D&B water services on site to perform test.  
Failed MIT.

Pumped between 12-15 bbls in casing string, could not get casing string to build pressure for the test. The Bradenhead had 91 psi at the start and was monitored during the total time frame and reached a final pressure of 101psi.

**Inspected Facilities**Facility ID: 258802 Type: WELL API Number: 045-07657 Status: PR Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Failed MIT  
Pumped between 12-15 bbls in casing string, could not get casing string to build pressure for the test. The Bradenhead had 91 psi at the start and was monitored during the total time frame and reached a final pressure of 101psi.

Corrective Action: Contact dnr\_cogccengineering@state.co.us with resolution plan.Date: 11/27/2018**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302365	Inspection photo 689302365	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4647370">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4647370</a>