

**FORM  
INSP**Rev  
X/15

# State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

11/17/2018

Submitted Date:

11/17/2018

Document Number:

689302376**FIELD INSPECTION FORM**
 Loc ID 334859 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Elsener,		COGCC.inspections@caerus oilandgas.com	<a href="#">all Piceance inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211532	WELL	PR	07/15/1998	GW	045-07292	BOULTON 33-6	PR
261014	WELL	PR	01/16/2003	GW	045-07925	SHIDELER 33-3A (F33)	PR
261015	WELL	PR	01/07/2003	GW	045-07926	SHIDELER 33-3 (F33)	PR
261016	WELL	PR	01/12/2003	GW	045-07927	BOULTON 33-6A (F33)	PR
263373	WELL	PR	01/21/2003	GW	045-08127	SHIDELER 33-4C2 (F33)	PR

**General Comment:**

This is a follow up inspection from Doc#689302105 . Required Corrective Action items noted in previous inspections have been satisfied.  
 1 Corrective action was not addressed. Storm water issue still outstanding.

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: 1-800-791-7691

Corrective Action:

Date:

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Bird Protectors

# 1

Comment:

Corrective Action:

Date:

Type: Plunger Lift

# 5

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

# 1

Comment:

Corrective Action:

Date:

Type: Vertical Heated Separator

# 5

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,

Comment:

Corrective Action:

Date:

**Paint**

Condition Adequate

Other (Content) Methanol tank

Other (Capacity) 1000 gallon

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:

Corrective Action:

Date:



<b>Inspected Facilities</b>				
Facility ID: <u>211532</u>	Type: <u>WELL</u>	API Number: <u>045-07292</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>				
Comment: <u>Well Producing on plunger lift</u>				
Corrective Action:			Date:	
Facility ID: <u>261014</u>	Type: <u>WELL</u>	API Number: <u>045-07925</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>				
Comment: <u>Well Producing on plunger lift</u>				
Corrective Action:			Date:	
Facility ID: <u>261015</u>	Type: <u>WELL</u>	API Number: <u>045-07926</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>				
Comment: <u>Well Producing on plunger lift</u>				
Corrective Action:			Date:	
Facility ID: <u>261016</u>	Type: <u>WELL</u>	API Number: <u>045-07927</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>				
Comment: <u>Well Producing on plunger lift</u>				
Corrective Action:			Date:	
Facility ID: <u>263373</u>	Type: <u>WELL</u>	API Number: <u>045-08127</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
<b><u>Producing Well</u></b>				
Comment: <u>Well Producing on plunger lift</u>				
Corrective Action:			Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Sediment is being moved off location on the west end of location. Sediment is filling the ditch that runs around location. See photo.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 10/26/2018

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302377	Inspection photo 689302377	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4649019">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4649019</a>