



00277825

"COPY"

Budget Bureau 42-R358.2.  
Approval expires 12-31-52.

(SUBMIT IN TRIPLICATE)

Land Office Denver  
Lease No. 023749-1  
Unit 1

BEST IMAGE  
AVAILABLE

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

6-1

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 15 D. M. 1951 1951, 1951

Well No. 2 is located 1900 ft. from N line and 300 ft. from E line of sec. 4

1/4 Sec. and Sec. No.      11N      97W      6th

Pueblo      Windsor      Colorado

(Field)      (County or Subdivision)      (State or Territory)

The elevation of the derrick floor above sea level is 6745 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

DST #15: TD 5116', packer set 5104', tool open 2 hours, puff when tool opened, pulsating blow to end of test. Recovered 90' mud, 430' oil, 2 gallons water. No HHP, FP 200 psi.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Mountain Fuel Supply Company

Address P. O. Box 1129  
Rock Springs, Wyoming

By D.M. Bowen

Title Manager, Producing Division