

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/03/2018

Submitted Date:

12/04/2018

Document Number:

679300025**FIELD INSPECTION FORM**
 Loc ID 323736 Inspector Name: Graber, Candice (Nikki) On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		NBL_DJBU_Inspections@NB LENERGY.COM	
Evans, Jacob		jacob.evans@nbenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
457385	SPILL OR RELEASE	AC	09/24/2018		-	Hambert RG 1,2,3	EI

General Comment:

COGCC Inspection in response to spill Document #401770112 reported by Operator. This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

Excavation ongoing at the time of inspection. COGCC met with Eagle personnel. Eagle provided a remediation summary and field screened a confirmation wall sampling at 7' bgs on the eastern wall.

Photos attached to document site condition at the time of inspection.

Location

Lease Road:			
Type	Access		
comment:	Heavy truck activity due to ongoing remediation. Access road well maintained; minimal rutting, no staining, no tracking.		
Corrective ActionL		Date:	

Overall Good: ☒

Emergency Contact Number:

Comment: Good

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	457385	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

--

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Other	Adequate		
Comment	Impacted soil being hauled to Buffalo Ridge Landfill.			
Corrective Action				Date:

Spill/Remediation:

Comment:	Ongoing excavation, no groundwater observed.			
Corrective Action:	Submit a Form 27 Site Investigation and Remediation Workplan for the removal of a buried/partially buried produced water vessel in accordance with Rule 905.b. The Form 27 Workplan may be submitted with the excavation and site assessment results, but should be submitted no later than 90 days from the Spill Report Date in order to resolve this release. The Form 27 for this release is due by 12/23/2018.			Date: 12/23/2018

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401860504	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4664221
679300027	Site Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4664214
679300028	Site Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4664215