

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/10/2018

Submitted Date:

12/11/2018

Document Number:

688800387**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
Hughes, Jim 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Baca, Matthew		matthew.baca@bpx.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	
Murray, Richard		g.richard.murray@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
459307	SPILL OR RELEASE	AC	12/10/2018		-	Richardson G 2	EI

General Comment:

[On December 10, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Spill/Release Point ID #459307. For more information regarding this release, please refer to Initial Spill/Release Report Document #401866521.](#)

Location**Lease Road:**

Type	Access		
comment:	Dirt and gravel access road. Release appeared to daylight on both sides of access road.		
Corrective ActionL		Date:	

Overall Good: ☒**Signs/Marker:**

Type	OTHER		
Comment:	Carsonite pipeline markers indicate pipelines cross access road near release point.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	459307	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

--

Environmental**Spills/Releases:**Type of Spill: PRODUCED WATEREstimated Spill Volume: 60Comment: [Please refer to Initial Spill/Release Report Document #401866521 for more information regarding this release.](#)Corrective Action: [Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.](#)Date: 01/11/2019Reportable: YESGPS: Lat 37.238919Long -107.697998Proximity to Surface Water: 500

Depth to Ground Water:

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

COGCC Comments

Comment	User	Date
<p>On December 10, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Spill/Release Point ID #459307. For more information regarding this release, please refer to Initial Spill/Release Report Document #401866521. BP representative Rick Stanley was on site during part of this inspection. Reportedly the water gathering line will be excavated on 12/11/18 to determine the root cause of this spill/release. Submit a supplemental Spill/Release report within ten days of discovery. Submit analytical results when they become available. The operator shall ensure that fluids from spill/release do not migrate any further. Provide all pipeline integrity data to the COGCC Engineering Integrity Supervisor, Mark Schlagenhauf, at (303) 894-2100 x5177 or mark.schlagenhauf@state.co.us.</p>	hughesjo	12/11/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
688800388	Inspection Photos	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4672201