

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401789484

Date Received:

10/09/2018

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87415

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Rowley, Darren

drowley@logosresourcesllc.com

Sessions, Tamra

tsessions@logosresourcesllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680603077

Inspection Date: 09/10/2018

FIR Submit Date: 09/14/2018

FIR Status: _____

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC

Company Number: 10679

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87415

LOCATION - Location ID: 312121

Location Name: CARR-N33N9W Number: 20SESW County: LA PLATA

Qtrqtr: SESW Sec: 20 Twp: 33N Range: 9W Meridian: N

Latitude: 37.084150 Longitude: -107.853320

FACILITY - API Number: 05-067-00 Facility ID: 214839

Facility Name: CARR Number: 1-M

Qtrqtr: SESW Sec: 20 Twp: 33N Range: 9W Meridian: N

Latitude: 37.084150 Longitude: -107.853320

CORRECTIVE ACTIONS:

1 ☒ CA# 118739

Corrective Action: As initial corrective action is addressed, a new corrective action date is applied. Additional stormwater controls and sediment removal/maintenance is needed to control erosion in the northern project area. Seeding or use of other slope stabilization products such as erosion control blankets on the diversion berm and slopes will help provide stabilization, as well as installation of sediment controls where stormwater flows into the project area.

Date: 10/19/2018

Response: CA COMPLETED

Date of Completion: 10/05/2018

Logos Operating, LLC cleaned out the ditch around the north side of the location and in front of the rock check

Operator Comment: dams. Erosion control blankets were added. Please see the attached photos.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Larissa Farrell

Signed: _____

Title: Environmental Technician

Date: 10/9/2018 1:53:24 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401789484	FIR RESOLUTION SUBMITTED
401789499	Photo 1
401789500	Photo 2
401789502	Photo 3
401789504	Photo 4

Total Attach: 5 Files