

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401873566  
Date Received:  
12/13/2018

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 26580  
Name of Operator: BURLINGTON RESOURCES OIL & GAS LP  
Address: 925 N ELDRIDGE PARKWAY  
City: HOUSTON State: TX Zip: 77079  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
LIANG YU	832-486-6014	LIANG.YU@COP.COM

COGCC INSPECTION SUMMARY:

FIR Document Number: 674902302  
Inspection Date: 12/06/2018 FIR Submit Date: 12/11/2018 FIR Status:

Inspected Operator Information:

Company Name: BURLINGTON RESOURCES OIL & GAS LP Company Number: 26580  
Address: 925 N ELDRIDGE PARKWAY  
City: HOUSTON State: TX Zip: 77079

LOCATION - Location ID: 449176

Location Name: King Number: 3-65 28-29 County:  
Qtrqr: NESE Sec: 28 Twp: 3S Range: 65W Meridian: 6  
Latitude: 39.758939 Longitude: -104.660816

FACILITY - API Number: 05-001-00 Facility ID: 449176

Facility Name: King Number: 3-65 28-29  
Qtrqr: NESE Sec: 28 Twp: 3S Range: 65W Meridian: 6  
Latitude: 39.758939 Longitude: -104.660816

CORRECTIVE ACTIONS:

1 ☒ CA# 120916

Corrective Action: Filtrex has not been properly installed, there is no overlap between connecting sections and daylight under the Filtrex. And this instance Filtrex needed to be trenched. Install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices near the facility by 12/18/2019

Date: 12/18/2018

Response: CA COMPLETED Date of Completion: 12/12/2018

Operator Comment: Filtrex installed properly as per required BMPs per Rule 1002.f. Please see attached photos of the filltrex after the corrections have been made.

COGCC Decision: Approved

COGCC Representative: Filtrex was installed properly upon reinspection on 12/18/18.

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Filtrex installed properly as per required BMPs per Rule 1002.f. Please see attached pictures.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: JOAN SWETLICK

Signed: \_\_\_\_\_

Title: REGULATORY

Date: 12/13/2018 1:03:23 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
401873566	FIR RESOLUTION SUBMITTED
401873576	Location ID: 449176, Inspection Document #: 674902302

Total Attach: 2 Files