

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401877668

Date Received:

12/17/2018

## FIR RESOLUTION FORM

### CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Baca, Matthew

970-764-7943

matthew.baca@bpx.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 680603092

Inspection Date: 09/13/2018

FIR Submit Date: 09/19/2018

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

### LOCATION - Location ID: 326108

Location Name: ELDRIDGE 30-1-N33N10W Number: 30SWNW County: LA PLATA

Qtrqtr: SWN Sec: 30 Twp: 33N Range: 10W Meridian: N

Latitude: 37.078285 Longitude: -107.980911

### FACILITY - API Number: 05-067-00 Facility ID: 215881

Facility Name: ELDRIDGE 30-01 Number: 1

Qtrqtr: SWN Sec: 30 Twp: 33N Range: 10W Meridian: N

Latitude: 37.078285 Longitude: -107.980911

### CORRECTIVE ACTIONS:

1 ☒ CA# 118864

Corrective Action: Remove either by mowing or otherwise control Russian thistles on the well pad.  
Remove black liner debris. Properly dispose of all waste and debris.

Date: 10/19/2018

Response: CA COMPLETED

Date of Completion: 12/04/2018

Operator  
Comment:

Actions Completed

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 118865

Corrective Action: Stormwater controls and managment is needed in multiple areas along the access road. Specifically areas where drainage crosses access need stabilization measures on banks and culverts repaired or another engineered solution employed. Stormwater flows along the access road need proper management toward ditches and de-energized appropriately.

Date: 11/02/2018

Response: CA COMPLETED

Date of Completion: 12/04/2018

Operator  
Comment: Actions Completed

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Actions Completed

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Matthew Baca

Signed: \_\_\_\_\_

Title: Construction Specialist

Date: 12/17/2018 3:44:15 PM

#### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401877668	FIR RESOLUTION SUBMITTED
-----------	--------------------------

401877673	Corrective Pics
-----------	-----------------

Total Attach: 2 Files