

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401874075

Date Received:

12/13/2018

## FIR RESOLUTION FORM

### CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name

Phone

Email

Rocky, TEP

COGCCInspectionReports@terraep.com

Murray, Richard

g.richard.murray@state.co.us

Pesicka, Conor

conor.pesicka@state.co.us

### COGCC INSPECTION SUMMARY:

FIR Document Number: 689302567

Inspection Date: 12/10/2018

FIR Submit Date: 12/10/2018

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

### LOCATION - Location ID: 323908

Location Name: SAVAGE Number: RMV 22-35 County: GARFIELD

Qtrqr: NWNE Sec: 35 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.487226 Longitude: -107.853232

### FACILITY - API Number: 05-045-00 Facility ID: 413230

Facility Name: SAVAGE Number: RWF 341-35

Qtrqr: NWNE Sec: 35 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.487226 Longitude: -107.853232

### CORRECTIVE ACTIONS:

1 ☒ CA# 120882

Corrective Action: Comply with Rule 603.f  
For unused, unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.

Date: 01/10/2019

Response: CA COMPLETED

Date of Completion: 12/12/2018

Flowline has been locked / tagged out. TEP wishes to leave line in place for future drilling needs at the RWF 331

Operator Comment: -35 well.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approval/passing of the FORM 4/FIRR, acknowledges that the Oil and Gas Conservation Commission has received the Notice.  
A field inspection will be conducted to evaluate compliance.

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Flowline has been locked / tagged out. TEP wishes to leave line in place for future drilling needs at the RWF 331-35 well.  
This CA is complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: \_\_\_\_\_

Title: TEP Environmental

Date: 12/13/2018 3:30:11 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
401874075	FIR RESOLUTION SUBMITTED
401874086	Flowline LO / TO

Total Attach: 2 Files