

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401912434
Date Received:
01/21/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 6720
Name of Operator: ROBERT L BAYLESS PRODUCER LLC
Address: 621 17TH ST STE 2300
City: DENVER State: CO Zip: 80293

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Trujillo, Helen		notices@rlbayless.com
Trujillo, Helen		htrujillo@rlbayless.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689801837
Inspection Date: 10/26/2018 FIR Submit Date: 10/26/2018 FIR Status:

Inspected Operator Information:

Company Name: ROBERT L BAYLESS PRODUCER LLC Company Number: 6720
Address: 621 17TH ST STE 2300
City: DENVER State: CO Zip: 80293

LOCATION - Location ID: 316765

Location Name: EILTS-BRADLEY-66N87W Number: 14NENE County: ROUTT
Qtrqtr: NENE Sec: 14 Twp: 6N Range: 87W Meridian: 6
Latitude: 40.482740 Longitude: -107.111020

FACILITY - API Number: 05-107-00 Facility ID: 232728

Facility Name: EILTS-BRADLEY Number: 1-14
Qtrqtr: NENE Sec: 14 Twp: 6N Range: 87W Meridian: 6
Latitude: 40.482740 Longitude: -107.111020

CORRECTIVE ACTIIONS:

1 CA# 119937

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 11/26/2018

Response: CA COMPLETED Date of Completion: 11/05/2018

TIGHTENED CONNECTIONS, REMOVED STAINED SOIL.

Operator
Comment:

COGCC Decision:

COGCC
Representative:

2 CA# 119938

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 11/26/2018

Response: CA COMPLETED

Date of Completion: 11/05/2018

Operator
Comment:

TIGHTEND FITTINGS, REMOVED STAINED SOIL.

COGCC Decision:

COGCC
Representative:

3 CA# 120003

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 11/26/2018

Response: CA COMPLETED

Date of Completion: 11/05/2018

Operator
Comment:

BLUE CHEMICAL BARREL REMOVED.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: SORRY ABOUT LATE RESPONSE. GOING THROUGH MY LIST OF THINGS TO DO AND THOUGHT WE HAD SUBMITTED THIS FIR. WORK COMPLETED NOVEMBER 2018.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: HELEN TRUJILLO

Signed: _____

Title: OFFICE MANAGER

Date: 1/21/2019 3:39:02 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files