

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/24/2019

Submitted Date:

01/24/2019

Document Number:

688401137**FIELD INSPECTION FORM**
 Loc ID 321259 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 39560Name of Operator: TOP OPERATING COMPANYAddress: 3609 S WADSWORTH BLVD STE 340City: LAKEWOOD State: CO Zip: 80235**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
Herring, Paul	303-727-9915	paul.herring@topoperating.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206541	WELL	PR	08/01/2018	GW	013-06036	TANAKA BROS 1	PR

**General Comment:**

**Inspected Facilities**

Facility ID: 206541 Type: WELL API Number: 013-06036 Status: PR Insp. Status: PR

**Complaint**

Comment: Inspection in response to complaint

Field Inspector Assigned: Randy Silver

Complaint Received:

Date: 1-21-2019 12:00AM

Location# 321259

Inspection Document # 200446881

Nature of complaint Noise

Field Inspector Actions:

On 1-22-2019, I was contact by supervisor Jason Gomez in reference to a complaint received by the COGCC in reference to noise. The Complainant stated the issues were coming from the Tanaka 1 production facility.

Complaint: The well is making a noise which it never used to make. During the day at various times and at night. It is a low growling noise that gets louder then diminishes at regular intervals. It sounds like there is a mechanical issue with pumping equipment? We have lived here 11 Years and have not heard this type of noise until the past 2 or 3 months.

On 1-23-20019, I made contact with the operator, at approximately 2:00PM who informed me he had been informed on 1-20-2019 of the problem from the complaint. He informed me he sent an employee on Monday the 21 to resolve the problem.

At time of inspection (1-23-2019) I did hear low vibrating noise from horizontal heated separator. Top Operating Company pumper called me at approximately 3:30PM to inform me he had adjusted the separator and the noise was gone. He stated they would come out each day and make sure the problem was resolved.

On 1-24-2019, I made contact with complainant at approximately 7:30am. I informed her that the operator was in the process of fixing problem.

A mechanical violation was issued to the operator for the issue DOC#688401131.

All information reviewed and site inspection were submitted to the COGCC for further review.

Corrective Action:

Date: