

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/18/2019

Submitted Date:

01/18/2019

Document Number:

679300089**FIELD INSPECTION FORM**
 Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
 _____ Graber, Candice (Nikki) _____ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Evans, Jacob		jacob.evans@nblenergy.com	
Inspections, All		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
447808	SPILL OR RELEASE	CL	12/27/2016		-	FRICO 17-22 SPILL/RELEASE	EI

General Comment:

This is an environmental inspection as a follow up to Document #401903850 on 1/14/2019 requesting NFA on Remediation #9969. Any corrective actions from previous inspections that have not been addressed are still applicable. Photos are attached to document site condition at the time of inspection.

There were no operator or contract environmental personnel on location at the time of this field inspection.

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Good

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		

In Containment: NoComment: None observed.☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	<u>Fenced and locked.</u>		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Spill/Remediation:**Comment: [Monitoring wells in place and in good condition.](#)Corrective Action: [Operator shall properly plug and abandon monitoring wells within 60 days of approval of NFA.](#)

Date: 03/19/2019

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401911080	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707949
679300092	Location Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707943
679300093	Location Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4707944