

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401919238

Date Received:

01/28/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Inspections, All		SanJuanCOGCC@bp.com
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 685305161
Inspection Date: 08/02/2018 FIR Submit Date: 08/03/2018 FIR Status:

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 325912

Location Name: STATE 1-36/35-8-N35N8W Number: 36SEnw County: LA PLATA
Qtrqtr: SENW Sec: 36 Twp: 35N Range: 8W Meridian: N
Latitude: 37.261537 Longitude: -107.699881

FACILITY - API Number: 05-067-00 Facility ID: 215553

Facility Name: STATE 01-36; 35-08 Number: 2
Qtrqtr: SENW Sec: 36 Twp: 35N Range: 8W Meridian: N
Latitude: 37.261537 Longitude: -107.699881

CORRECTIVE ACTIIONS:

1 CA# 117808

Corrective Action: Locate and mark deadmen to comply with Rule 1003.a. Date: 09/03/2018

Response: CA COMPLETED Date of Completion: 08/16/2018

Operator Comment: Action Complete: Rebuilt diversion ditch/berm at base of slope. Removed old well sign. Built two new rock run-downs to code. Seeded disturbed areas and removed miscellaneous trash. See attached photos

COGCC Decision:

COGCC
Representative:

2 CA# 117809

Corrective Action: Install or repair required BMPs to comply with Rule 603.f.

Date: 09/03/2018

Response: CA COMPLETED

Date of Completion: 08/16/2018

Operator Comment: Action Complete: Rebuilt diversion ditch/berm at base of slope. Removed old well sign. Built two new rock run-downs to code. Seeded disturbed areas and removed miscellaneous trash. See attached photos

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Action Complete: Rebuilt diversion ditch/berm at base of slope. Removed old well sign. Built two new rock run-downs to code. Seeded disturbed areas and removed miscellaneous trash. See attached photos

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 1/28/2019 7:14:03 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401919244	CA and Comment closure photos
-----------	-------------------------------

Total Attach: 1 Files