

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/04/2019

Submitted Date:

02/06/2019

Document Number:

682504490

FIELD INSPECTION FORM

Loc ID 453784 Inspector Name: Trujillo, Aaron On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Findings:

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		chris.binschus@state.co.us	
Arthur, Denise		denise.arthur@state.co.us	
,		regulatory@foundationenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
111646	PIT	AC			-	ANDREWS PIT (2 WELLS)	RI
453785	TANK BATTERY	AC	01/22/2018		-	Andrews Tank Battery Facility	RI

General Comment:

This is a follow-up Final Reclamation Inspection for the tank battery location associated with PA Well API#123-14767. The tank battery location is in non-cropland. A separate Final Reclamation Inspection will be submitted for the well location which is in cropland. Refer to the attached inspection photos for more detail.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Inspection #684904055, #682403219 and #682504197 required operator to comply with Rule 603.f and remove all oil and gas equipment and other associated unused equipment. Corrective action has not been addressed.		
Corrective Action:	Comply with Rule 603.f. Corrective actions from the previous inspection were not resolved; therefore, the corrective action date on this inspection will remain the same from the previous inspection.		Date: <u>11/17/2017</u>

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 111646 Type: PIT API Number: - Status: AC Insp. Status: RI

Facility ID: 453785 Type: TANK API Number: - Status: AC Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed **Fail** _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed **Fail** _____ Locations, facilities, roads, recontoured _____

Compaction alleviation **Fail** _____ Dust and erosion control _____

Non cropland: Revegetated 80% **Fail** _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action:

Date **11/15/2017**

Corrective Action (CA)#1: Perform reclamation in accordance to Rule 1003 and 1004 standards as soon as possible. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. The Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards. CA #2: Provide documentation the surface owner asked for the proposed seed mixture. Corrective action date is back dated using the reclamation complete date of 11/15/2017, stated on the Form 27.

Overall Final Reclamation **Fail** Well Release on Active Location Multi-Well Location

COGCC Comments

Comment	User	Date
Due to ongoing compliance issues, this location is being referred for enforcement.	trujilloam	02/06/2019
RECLAMATION COMMENT This location is not in compliance with Rules 1003 and 1004.. Operator appears to have backfilled the pit, however, it does not appear as though operator provided notice per Form 27 #401436081 COAs. Operator has failed to remove equipment per Rule 1004. Operator has failed to complete final reclamation activities within the first favorable season per Rule 1003.e.(2), Rule 1004 and corrective actions. Operator has failed to complete final reclamation activities by the reclamation complete date of 11/15/2017, stated on the Form 27. Operator has failed to provide documentation that the surface owner asked for the proposed seed mixture. In addition, oil contaminated soils evident around tanks laying on side and left on location, and a barrel containing petroleum distillates/Isopropyl alcohol is not within secondary containment. Corrective actions have not been addressed and remain applicable.	trujilloam	02/06/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682504491	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4726338