

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/13/2019

Submitted Date:

02/14/2019

Document Number:

682600622**FIELD INSPECTION FORM**Loc ID 321682 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 17180Name of Operator: CITATION OIL & GAS CORPAddress: 14077 CUTTEN RDCity: HOUSTON State: TX Zip: 77269**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Elsom, Lee Ann	281-891-1577	lelsom@cogc.com	
Sutphin, Dirk		dirk.sutphin@state.co.us	
Ward, Sharon		sward@cogc.com	
,		dnr_cogccenforcement@state.co.us	COGCC Enforcement
,		dnr_cogccengineering@state.co.us	COGCC Engineering
Kennedy, Herschel	719-767-8851 off/51922	hkennedy@cogc.com	719-340-1150 cell

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207769	WELL	PR	05/01/2017	OW	017-06704	UPRC-SIMPSON 12-19 1	EI

General Comment:

This is a follow up inspection to COGCC Inspection #682600615 which found the Simpson 12-19 well venting gas via a 1 inch valve on 1/31/2019. Operator was informed of venting and stated they would get someone out to stop the venting on 1/31/2019. Follow up inspection on 2/13/2019 found that the operator had placed a threaded plug in the valve but methane gas was still venting through the plug (see attached video).

Summary of issues:

Operator is venting methane gas from well without prior approval from COGCC Engineering.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	YES		
Comment:	Gas being vented or flared during non-upset condition without prior approval from COGCC. I observed a stream of gas being vented and a 4 gas meter detected methane gas. See attached video.		
Corrective Action:	Since the flaring or venting occurred after flowback without approval, contact the COGCC Area Engineer for next steps per Rule 912.b. if operator intends to continue venting. If operator intends to cease venting operator should repair or replace valve and/or plug.	Date:	02/02/2019

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 207769 Type: WELL API Number: 017-06704 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682600630	Venting video	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4734458
682600631	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4734459