

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401942015  
Date Received:  
02/15/2019

FIR RESOLUTION FORM

CA Summary:  
3 of 3 CAs from the FIR responded to on this Form  
3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672  
Name of Operator: TIMBER CREEK OPERATING LLC  
Address: 1001 17TH STREET #1000  
City: DENVER State: CO Zip: 80202  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Santistevan, Vince	719-845-2102/719-680-9705	vincasantistevan@tcenergy.us
Amato, Joseph	719-845-2110/719-859-2263	josephamato@tcenergy.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 688401103  
Inspection Date: 01/18/2019 FIR Submit Date: 01/18/2019 FIR Status:

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672  
Address: 1001 17TH STREET #1000  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 308409

Location Name: GOLDEN EAGLE-633S67W Number: 28SESE County: LAS ANIMAS  
Qtrqtr: SESE Sec: 28 Twp: 33S Range: 67W Meridian: 6  
Latitude: 37.138560 Longitude: -104.885170

FACILITY - API Number: 05-071-00 Facility ID: 271279

Facility Name: GOLDEN EAGLE Number: 28-16  
Qtrqtr: SESE Sec: 28 Twp: 33S Range: 67W Meridian: 6  
Latitude: 37.138560 Longitude: -104.885170

CORRECTIVE ACTIONS:

1  CA# 121857

Corrective Action: Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A Date: 02/18/2019

Response: CA COMPLETED Date of Completion: 02/15/2019

Operator Comment: Stained soil has been cleaned up and removed from location.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

[Empty text box for COGCC Representative]

**2**  CA# 121858

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 01/19/2019

Response: CA COMPLETED

Date of Completion: 02/19/2019

Operator Comment: packing repaired

COGCC Decision: Approved pending re-inspection

COGCC Representative:

[Empty text box for COGCC Representative]

**3**  CA# 121859

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e

Date: 02/18/2019

Response: CA COMPLETED

Date of Completion: 02/15/2019

Operator Comment: Stained soil has been cleaned up and removed from location.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

[Empty text box for COGCC Representative]

**OPERATOR COMMENT AND SUBMITTAL**

Comment: All CA's are complete for this location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Joseph Amato

Signed: \_\_\_\_\_

Title: Regulatory Manager

Date: 2/15/2019 1:39:53 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
401942015	FIR RESOLUTION SUBMITTED
401942037	Location Photos

Total Attach: 2 Files