

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401959319

Date Received:

03/04/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Abby Bazin

720-587-2356

abby.bazin@nbenergy.com

Tesla Dougherty

970-304-5245

tesla.dougherty@nbenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682504527

Inspection Date: 02/27/2019

FIR Submit Date: 02/28/2019

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

LOCATION - Location ID: 460414

Location Name: LD07-01 MULTI Number: \_\_\_\_\_ County: \_\_\_\_\_

Qtrqtr: NENE Sec: 7 Twp: 9N Range: 58W Meridian: 6

Latitude: 40.772200 Longitude: -103.901750

FACILITY - API Number: 05-123-00 Facility ID: 460414

Facility Name: LD07-01 MULTI Number: \_\_\_\_\_

Qtrqtr: NENE Sec: 7 Twp: 9N Range: 58W Meridian: 6

Latitude: 40.772200 Longitude: -103.901750

CORRECTIVE ACTIONS:

1 CA# 122770

Corrective Action: Install required stormwater and erosion control BMPs in accordance with Rule 1002.f and stabilize soil stockpiles in accordance with 1002.c

Date: 02/27/2019

Response: CA COMPLETED

Date of Completion: 03/01/2019

Operator  
Comment:

Noble has prepared the attached response and wishes to continue discussing these issues with COGCC staff.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**2** CA# 122771

Corrective Action: Operator shall continue compliance with rule 1002.e and 1002.f and maintain BMPs to ensure the disturbance area remains stabilized/protected from erosion degradation

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 02/28/2019

Operator  
Comment:

Noble has prepared the attached response and wishes to continue discussing these issues with COGCC staff.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**3** CA# 122772

Corrective Action: Install required stormwater and erosion control BMPs in accordance with Rule 1002.f

Date: 02/27/2019

Response: CA COMPLETED

Date of Completion: 02/28/2019

Operator  
Comment:

Noble has prepared the attached response and wishes to continue discussing these issues with COGCC staff.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tesla Dougherty

Signed: \_\_\_\_\_

Title: EHS Specialist

Date: 3/4/2019 1:50:17 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401959334	LD07-01 Pad Response
-----------	----------------------

Total Attach: 1 Files