

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/07/2019

Submitted Date:

03/07/2019

Document Number:

693900030**FIELD INSPECTION FORM**Loc ID 439554 Inspector Name: ROY, CATHERINE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10412Name of Operator: AUSCO PETROLEUM INCAddress: 113 N SANTA FE AVENUECity: FLORENCE State: CO Zip: 81226**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Goss, Aaron	303-495-0327	agoss@fremontpetroleum.com	All Inspections
Harkins, Liz	303-233-2232/719-429-4513	Lharkins@austinexploration.com	All Inspections
Hart, Tim		thart@fremontpetroleum.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
439553	WELL	PR	07/01/2016	LO	043-06228	Marco Polo 1	RI

General Comment:[This is an interim reclamation and stormwater inspection.](#)

Inspected Facilities									
Facility ID:	439553	Type:	WELL	API Number:	043-06228	Status:	PR	Insp. Status:	RI

--

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: Project area is surrounded by open pinyon juniper woodland and cholla shrub, and grassland. Revegetation has been initiated within the eastern and southeastern project area, and outer fill slopes.**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____

Comment Corrective Action Date _____1002b. SOIL REMOVAL AND
SEGREGATION _____Comment Corrective Action Date _____

1002c. PROTECTION OF SOILS _____

Comment Corrective Action Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment Corrective Action Date _____1003a. Waste and Debris removed? PassComment Corrective Action Date _____Unused or unneeded equipment onsite? PassComment Corrective Action Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment Corrective Action Date _____

Guy line anchors marked? _____

Comment Corrective Action Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Revegetation has been initiated within the eastern and southeastern project area, as well as the northern fill slopes. At this time in the season, it is not apparent whether disturbance in northwestern project area, off of the well pad, has been revegetated as it is largely vegetated with annual weeds and forbs at this time.

Corrective Action

Revegetation needs to be conducted within the disturbance area adjacent to the access road, northwest of the well pad within the spring 2019 seeding window, by April 1, 2019. If this area was recently seeded, revegetation needs to be monitored and if desirable vegetative cover is not increasing, then additional seeding activities will be required by November 1, 2019.

Date **04/01/2019**

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:		
Corrective Action:		Date
Overall Final Reclamation	Well Release on Active Location <input type="checkbox"/>	Multi-Well Location <input type="checkbox"/>

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Erosional rilling and gullyng is occurring within the northern fill slope. Erosion is also occurring within the eastern project area where concentrated stormwater runoff flows north toward a nearby stream. Cut-slope within the southern project area is vertical and needs stabilization. Erosion is also occurring along the access road where it enters the southern edge of the well pad. See attached photos.

Corrective Action: Stormwater controls need to be installed to stabilize erosion within the project area.

Date: 04/12/2019

Pits: ☐ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	442152	400721660	
	442152	400721660	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693900032	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4755265