

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/27/2019

Submitted Date:

03/01/2019

Document Number:

695100241**FIELD INSPECTION FORM**

Loc ID 307873 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10084Name of Operator: PIONEER NATURAL RESOURCES USA INCAddress: 5205 N O'CONNOR BLVD STE 200City: IRVING State: TX Zip: 75039**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ash, Margaret		margaret.ash@state.co.us	
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.co m	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258678	WELL	PR	12/04/2003	GW	071-07123	LORENCITO 10-2-34-67	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	LOCATION SIGN IS MISSING REQUIRED INFORMATION. NO EMERGENCY CONTACT INFORMATION POSTED.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	03/27/2019

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	DISCHARGING PRODUCED WATER WHILE BYPASSING SEPARATOR.		
Corrective Action:	IMMEDIATELY BEGIN TREATING PRODUCED WATER PRIOR TO DISPOSING. COMPLY WITH COGCC RULE 907. e. (2)	Date:	
Type	OTHER		
Comment:	NO RECORDS FOR SURFACE DISCHARGE FOUND IN COGCC DATABASE.		
Corrective Action:	Provide documents listed under 907.e(2)E to Field Inspection Unit Manager with 24 hours.	Date:	
Type	OTHER		
Comment:	APP. 12" BY 24" SECTION OF IMPACTED SOIL NEAR WELLHEAD. SEE LOCATION PHOTOS. REMOVE AND PROPERLY DISPOSE OF IMPACTED SOIL.		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.	Date:	04/01/2019

Overall Good: ☐

Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Equipment:			corrective date
Type: Other	# 1		
Comment:	BREADENHEAD IS PLUMBED TO SURFACE		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	LAST CAL. 11/13/18		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities				
Facility ID: 258678	Type: WELL	API Number: 071-07123	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Environmental**Spill/Remediation:**Comment: Corrective
Action: Date: Emission Control Burner (ECB): Comment: Pilot: Wildlife Protection Devices (fired vessels): **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401957295	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4750517
695100266	LOCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4750510