

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/28/2019

Submitted Date:

03/04/2019

Document Number:

678302414

**FIELD INSPECTION FORM**

Loc ID 333125 Inspector Name: GINTAUTAS, PETER On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

**Findings:**

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Lara-Mesa, Susana	303-825-4822	cogcc@kpk.com	<a href="#">Eng'g Project Mgr</a>
Contact, General		regulatory@foundationenergy.com	<a href="#">All inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240923	WELL	PR	10/01/2018	GW	123-08711	PARKER 2	EI

**General Comment:**

site investigation and remediation project 5013 remains open at this location since 2010 with no updates or reports of activities and if justified no request for closure of project received from either operator.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		
Crude Oil				
Comment:	Inspection 200205303 in 2009 indicates crude spilled on location and need for removal of impacted soils. Approved site investigation and remediation plan 5013 submitted in 2010 as corrective action for failed inspection 200205302 indicates soil samples to be collected and analyzed following removal of oil saturated soils to show compliance with Tble 910-1 thresholds. No results to document removal found in COGCC records.			
Corrective Action:	submit documentation of remediation progress since 2010 by supplemental eForm 27 to either request closure (if soils analysis indicates that Table 910-1 thresholds are met) or revised plan to address impacts noted in 2009 inspection			Date: 04/04/2019

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 240923 Type: WELL API Number: 123-08711 Status: PR Insp. Status: EI

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401958584	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4751596">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4751596</a>